

Ashe County Schools is requesting quotes for the replacement of two (2) softball dugouts located at Ashe County Middle School, 255 Northwest Lane, Warrensville, NC 28693 that were damaged during Hurricane Helene. All work must comply with FEMA public assistance procurement and construction standards including Environmental Protective Agency regulations.

Scope of Work

The Contractor shall furnish all labor, equipment, materials, permits, supervision, and services required to:

- Remove and dispose of existing damaged dugouts in compliance with environmental and safety regulations.
- Rebuild dugouts per the detailed specifications, plans, and drawings attached as Exhibit A.
- Ensure compliance with applicable building codes, ADA requirements, and FEMA hazard mitigation and resiliency standards.
- Meet any site-specific requirements outlined by the Owner or FEMA representatives.

For questions or to schedule a site visit, contact:

Jody Corum

Maintenance Director


Email: jody.corum@ashe.k12.nc.us

Phone: (336) 246-7175


Quotes will be received until June 12, 2025.

ATTACHMENT A



FOUNDATION & MASONRY WALL PLAN




ROOF FRAMING PLAN



3D ELEVATION



1/51 - FOOTING & WALL DETAIL
SCALE: 3/4" = 1'-0"



SIMPSON STRONG-TIE POST CAP MODEL # ACH6Z(END)
CONNECTION HARDWARE FOR LVL CAP BEAM TO 6 X 6 COLUMN

NOTE: THIS DUGOUT LAYOUT IS FOR THE DUGOUT ALONG THE 3RD BASE LINE. THE DUGOUT ALONG THE FIRST BASE LINE WILL BE A MIRRORED LAYOUT OF THIS PLAN.



S-1

SHEET:

1/2" = 1'-0"

SCALE:

DATE: 4/3/2025

DATE:

DRAWINGS PROVIDED BY:
LURAY ENGINEERING
SERVICES P.C.

ASHE COUNTY
MIDDLE SCHOOL

SOFTBALL DUGOUT
PLAN

REVISION TABLE		REVISION TABLE	
NUMBER	DATE	REVISOR	DESCRIPTION